

ON-ITM01P Infrared Thermometer



Advantages



Quick Measurement



High Accuracy



Alarm Function



3 Installation Methods



°C/°F Unit Available



Data output



Technical Data

Method of measurement	Sensitivity sensor distance sensor	Operating mode	Surface mode /body mode / Count mode
Temperature Unit	°C/°F	Surface temperature measurement range	10--50°C
Accuracy	±0.2 (34~45°C)	Range of Body Mode temperature	35--42°C
Measuring distance	5 ~ 10 cm	Environment temperature	10--40°C
Display	2.8-inch LCD screen	Counting capacity	9999 times
Install Method	Nail hook/bracket fixing	Record temperature data	Support to review 30 sets of data
Power supply	USB /4 AA batteries	Alarm Function	Flash+sound alarm for about 10 seconds
Response time	0.5s	IO signal output	Support(switch signal / pulse signal)
Working band	5um	Body storage <input checked="" type="checkbox"/>	Connect to the computer <input checked="" type="checkbox"/>
Standby time	30s	Volume setting <input checked="" type="checkbox"/>	Voice broadcast <input checked="" type="checkbox"/>
Product Size	170*115*140mm	Backlight switch <input checked="" type="checkbox"/>	Standby <input checked="" type="checkbox"/>
Net weight	303g	Upper alarm limit <input checked="" type="checkbox"/>	Whether to support charging <input checked="" type="checkbox"/>

Quick measurement

Accurate feedback

Fever alarm

© Accurate temperature measurement

CE FC RoHS